

Amendments to the Specification

Please amend Table I on page 19 of the specification and Table 2 on page 20 of the specification (deleting rows corresponding to examples A-1 and D-1 as shown on the following pages:

[Table 1]

Symbol	Chemical components (mass%)											
	C	Si	Mn	Al	Cu	Ni	Cr	Mo	V	Nb	Ti	B
A-1	<u>0.15</u>	<u>0.25</u>	<u>1.30</u>	<u>0.023</u>	<u>0.005</u>	<u>0.006</u>	<u>0.004</u>	<u>0.006</u>	<u>0.005</u>	<u>0.004</u>	<u>0.002</u>	<u>0.0005</u>
B-1	0.14	0.35	1.25	0.030	0.004	0.005	0.004	0.004	0.007	0.005	0.003	0.0006
C-1	0.12	0.31	1.12	0.025	0.006	0.007	0.006	0.005	0.006	0.006	0.001	0.0007
D-1	<u>0.12</u>	<u>0.28</u>	<u>1.08</u>	<u>0.020</u>	<u>0.005</u>	<u>0.005</u>	<u>0.004</u>	<u>0.004</u>	<u>0.005</u>	<u>0.006</u>	<u>0.003</u>	<u>0.0005</u>
E-1	0.08	0.41	0.85	0.019	0.007	0.006	0.005	0.005	0.004	0.004	0.012	0.00150
F-1	0.13	0.32	0.72	0.025	0.005	0.020	0.410	0.560	0.303	0.071	0.001	0.00005
G-1	0.07	0.34	0.80	0.036	0.540	0.650	0.005	0.005	0.215	0.056	0.020	0.00210
H-1	<u>0.005</u>	<u>0.11</u>	<u>0.55</u>	<u>0.018</u>	<u>0.005</u>	<u>0.004</u>	<u>0.004</u>	<u>0.003</u>	<u>0.005</u>	<u>0.004</u>	<u>1.575</u>	<u>0.001</u>
I-1	<u>0.32</u>	<u>0.05</u>	<u>0.62</u>	<u>0.022</u>	<u>0.004</u>	<u>1.640</u>	<u>0.004</u>	<u>0.004</u>	<u>0.005</u>	<u>0.003</u>	<u>0.002</u>	<u>0.0004</u>
J-1	0.05	<u>0.005</u>	0.48	0.034	0.006	0.004	0.005	0.005	<u>0.984</u>	0.005	0.003	0.0005
K-1	0.17	<u>1.65</u>	0.22	0.027	0.003	0.006	<u>2.130</u>	0.006	0.005	0.004	0.002	0.0006
L-1	0.11	0.32	<u>0.06</u>	0.035	0.004	0.005	<u>0.006</u>	<u>2.572</u>	0.004	0.006	0.001	0.0004
M-1	0.10	0.21	<u>3.14</u>	0.041	<u>1.520</u>	0.003	0.007	0.004	0.006	0.004	0.003	0.0003
N-1	0.12	0.45	1.57	<u>0.005</u>	0.005	0.007	0.005	0.006	0.005	0.006	0.002	<u>0.01025</u>
O-1	0.14	0.15	1.25	0.120	0.004	0.005	0.005	0.004	0.004	0.005	0.534	0.00004

[Table 2]

Symbol	Average ferrite grain size (μm)	Microstructure			Tensile properties				
		Spheroidized or not	Cementite or pearlite	Average grain size (μm)	YS (MPa)	TS (MPa)	YR (%)	YS (MPa)	TS (MPa)
Invention example									
A-1	59	0	23	304	511	60	544	610	89
B-1	41	1	10	281	506	55	423	558	76
C-1	48	0	18	278	479	58	492	570	86
D-1	54	1	9	254	475	53	388	523	74
E-1	68	0	19	250	438	57	467	530	88
F-1	45	0	18	283	518	55	497	609	82
G-1	25	1	4	240	436	55	334	470	71
H-1	33	0	25	130	325	40	398	425	94
I-1	30	0	31	344	564	61	648	673	96
J-1	17	0	38	130	350	37	425	468	91
K-1	24	0	35	418	571	73	668	685	97
L-1	18	0	11	261	409	64	465	484	96
M-1	17	0	32	321	479	67	567	589	96
N-1	84	0	44	254	470	54	586	595	98
O-1	10	0	5	336	452	74	477	509	94

Comparative example
 Spheroidized or not
 0: Not spheroidized
 1: Spheroidized